

• Outfall near confluence – Downstream near outfall to SCR looking downstream



• Outfall near confluence – 200' upstream photo 96 looking downstream



• Service Road 18A – Downstream side of bridge looking upstream



• Service Road 18A – Upstream side of bridge looking downstream



 Service Road 18A – Downstream side of bridge looking downstream at rock filled wall



• Service Road 18A – Upstream side of bridge looking upstream



• Service Road 18B – Downstream side of bridge looking upstream



• Service Road 18B – Upstream side of crossing looking downstream



• Service Road 18B – Upstream side of crossing looking upstream



• Los Angeles Road – Downstream side of crossing looking upstream



• Los Angeles Road – Downstream side of crossing looking downstream



• Los Angeles Road – Upstream side of crossing looking downstream



 Los Angeles Road – Upstream side of crossing looking upstream at tributary channel



Los Angeles Road – Upstream side of crossing showing tributary and RD confluence looking North



• Service Road 18D – Downstream side of crossing looking upstream



• Service Road 18D –Upstream side of crossing looking downstream



• Service Road 18D – Upstream side of crossing looking upstream



• California Avenue – Downstream side of crossing looking upstream



• California Avenue – Upstream side of crossing looking downstream



• California Avenue – Upstream side of crossing looking upstream



• North of South Mountain Road – Downstream side of crossing looking upstream



• North of South Mountain Road –Upstream side of crossing looking downstream



• North of South Mountain Road – Upstream side of crossing looking upstream concrete channel bottom is eroding



• South Mountain Road – Downstream side of crossing looking upstream



• South Mountain Road –Upstream side of crossing looking downstream



• South Mountain Road – Upstream side of crossing looking upstream