MATCH TO SHEET NO. 1

VICINITY MAP

SCALE 0 5 10 15 20 25 MILES

MATCH TO SHEET No. 3

N

LEGEND

Limit of flood due to dam failure with the pool at spillway crest, elevation 2238 feet NGVD.

5 Average overbank depth in feet at cross section.

Cross Section

2000 0 2000 4000 6000

SCALE IN FEET

Contour interval 10, 20, and 25 feet
National Geodetic vertical datum of 1929

Source of base map: U. S. Geological Survey
7.5 minute series

NOTE: The inundated areas shown on this map reflect events of an extremely remote nature. These results are not in any way intended to reflect upon the integrity of the San Antonio Dam.

U.S. ARMY ENGINEER DISTRICT, LOS ANGELES
CORPS OF ENGINEERS
LOS ANGELES, CALIFORNIA

SAN ANTONIO DAM
EMERGENCY PLAN
INUNDATION MAP

FEBRUARY 1986 PLATE NO. 2

MATCH TO SHEET NO. 4