MATCH TO PLATE NO. 2





N

LEGEND

Limit of flood due to dam failure with the pool at top of spillway gates (in raised position), elevation 710.0 feet NGVD.

5 Average overbank depth in feet of cross section.

Cross Section

2000 0 2000 4000 6000
SCALE IN FEET

Contour Interval 20 and 25 feet
National Geodetic vertical datum of 1929

Source of base map: U. S. Geological Survey 7.5 minute series

NOTE: The inundated areas shown on this map reflect events of an extremely remote nature. These results are not in any way intended to reflect upon the integrity of the Sepulveda Dam.

U.S. ARMY ENGINEER DISTRICT, LOS ANGELES
CORPS OF ENGINEERS
LOS ANGELES, CALIFORNIA

SEPULVEDA DAM EMERGENCY PLAN

INUNDATION MAPS

JULY 1986

PLATE NO. 3

MATCH TO PLATE NO. 5