



N

LEGEND

Limit of flood due to dam failure with the pool at top of spillway gates, elevation 229.0 feet.

5 Average overbank depth in feet at cross section.

Cross Section

2000 0 2000 4000 6000
SCALE IN FEET

Contour interval 10 and 20 feet
National Geodetic Vertical Datum of 1929

Source of base map: U. S. Geological Survey 7.5 minute series

NOTE: The inundated areas shown on this map reflect events of an extremely remote nature. These results are not in any way intended to reflect upon the integrity of the Whittier Narrows Dam.

U.S. ARMY ENGINEER DISTRICT, LOS ANGELES
CORPS OF ENGINEERS
LOS ANGELES, CALIFORNIA

WHITTIER NARROWS DAM
EMERGENCY PLAN
INUNDATION MAP

AUGUST 1985

PLATE NO. 1