



## LEGEND

Limit of flood due to dam failure with the pool of upstream crest, elevation 2230 feet NGVD

Average overbank depth in feet of cross section

Cross Section

2000 0 2000 4000 6000  
SCALE IN FEET

Contour Interval 20 and 25 feet  
National Geodetic vertical datum of 1929  
Source of base map: U.S. Geological Survey  
7.5 minute series

NOTE: The inundated areas shown on this map reflect events of an extremely remote nature. These results are not in any way intended to reflect upon the integrity of the San Antonio Dam.

U.S. ARMY ENGINEER DISTRICT, LOS ANGELES  
CORPS OF ENGINEERS  
LOS ANGELES, CALIFORNIA

### SAN ANTONIO DAM EMERGENCY PLAN INUNDATION MAP