



VICINITY MAP

SCALE 1 MILE 9 7 5 3 MILES



LEGEND

Line of flood due to dam failure with the pool at spillway crest, elevation 475.0 feet.

Average overbank depth in feet of cross section.

Cross Section

2000 4000 6000
SCALE IN FEET

Contour Interval 20 and 25 feet.
Horizontal datum: Vertical datum of 1929
Source of base maps: U. S. Geological Survey
7.5 minute series

NOTE: The inundated areas shown on this map reflect events of an extremely remote nature. These results are not in any way intended to reflect upon the integrity of the Carbon Canyon Dam.

U. S. ARMY ENGINEER DISTRICT, LOS ANGELES
CORPS OF ENGINEERS
LOS ANGELES, CALIFORNIA

CARBON CANYON DAM
EMERGENCY PLAN
INUNDATION MAPS

JUNE 1985

PLATE NO. 2