



LEGEND

Limit of flood due to dam and/or saddle dike failure with the pool at spillway crest, elev. 5675.0 feet.

5

Average overbank depth in feet
of cross section.

CCCCCCCCCCCCCCCC Cross Section

0 2000 4000 6000
SCALE IN FEET

Contour Interval 20 and 40 feet
National Geodetic Vertical Datum of 1929

Source of base map: U.S. Geological Survey
7.5 minute series

NOTE: The inundated areas shown on
this map reflect events of an extremely
remote nature. These results are not
in any way intended to reflect upon the
integrity of the Pine Canyon Dam.

U. S. ARMY ENGINEER DISTRICT, LOS ANGELES
CORPS OF ENGINEERS
LOS ANGELES, CALIFORNIA

PINE CANYON DAM EMERGENCY PLAN INUNDATION MAP