

# **Attachment B**

## **B. Field Investigation Photographs**

This page intentionally left blank



**Photo 1 – D/S Face of RCB Culvert under Pacific Park Drive**



**Photo 2 – Looking D/S along Aliso Creek from Pacific Park Drive Culvert**





**Photo 3 – Grouted Riprap across Streambed Possibly for Utility Crossing (approximately 180' D/S of Pacific Park Drive Culvert D/S Face)**



**Photo 4 – Skate Park / Soccer Field to be Relocated (on East Bank)**





**Photo 5 – Access Road along East Bank of Aliso Creek near Skate Park/Soccer Field**



**Photo 6 – Drop Structure to be Removed, Located U/S of Aliso Creek Road Bridge**





**Photo 7 – Drop Structure to be Removed, Located U/S of Aliso Creek Road Bridge (Close-up)**



**Photo 8 – Looking D/S along Aliso Creek at Aliso Creek Road Bridge from Drop Structure to be Removed**





**Photo 9 – Looking at U/S Face of Aliso Creek Road Bridge**



**Photo 10 – Looking U/S along Aliso Creek from Aliso Creek Road Bridge**





**Photo 11 – Looking U/S at SD outlet on West Bank (Aliso Creek Road Bridge to the Right of Photo)**



**Photo 12 – Drop Structure to be Removed, Located D/S of Aliso Creek Road Bridge**





**Photo 13 – Grouted Riprap Drop Structure to be Removed, Located D/S of Aliso Creek Road**



**Photo 14 – D/S Face of AWMA Road Bridge**





**Photo 15 – Grouted Riprap Drop Structure Immediately D/S of AWMA Road Bridge**



**Photo 16 – Looking U/S along Aliso Creek from AWMA Road Bridge**





**Photo 17 – Existing RCB Culvert along Sulphur Creek underneath Alicia Parkway**



**Photo 18 – Looking D/S along Sulphur Creek between Aliso Creek Confluence and Ex. RCB underneath Alicia Parkway**





**Photo 19 – Pedestrian Streambed Access Point to be Replaced (Approximately 650' D/S of Sulphur Creek Confluence)**



**Photo 20 – Looking D/S from Top of ACWHEP Structure**





**Photo 21 – Looking U/S at D/S End of Outlet Pipe through ACWHEP Structure**



**Photo 22 – D/S End of Wood Canyon Creek Culverts under Paved Trail at Aliso Creek Confluence  
((3) 42”(W) x 30”(H) Elliptical CMPs)**





**Photo 23 – Looking D/S at Aliso Creek Confluence from Wood Canyon Creek Culverts**



**Photo 24 – Abandoned Oxbow (Looking from the West Bank)**





**Photo 25 – Looking U/S along Aliso Creek from SOCWA Coastal Treatment Plant Bridge**



**Photo 26 – Looking at D/S Face of SOCWA Coastal Treatment Plant Bridge**





**Photo 27 – Looking U/S along Aliso Creek Low Flow Channel underneath SOCWA Coastal Treatment Plant Bridge**



**Photo 28 – U/S Limit of Grouted Riprap underneath SOCWA Coastal Treatment Plant Bridge**





**Photo 29 – D/S Limit of Grouted Riprap underneath SOCWA Coastal Treatment Plant Bridge**



**Photo 30 – Typical View of Un-used Parking Lot across Alicia Parkway for Skate Park/Soccer Field Relocation**



**This page intentionally left blank**